

Photos of Fence Damage
San Jacinto River Waste Pits
June 18, 2014



Photo 1: Hole in fence at entrance gate north of and adjacent to I-10 (20140618_5.JPG)



Photo 2: Location of hole in fence shown in Photo 1 (20140618_7.JPG)



9674066

Photos of Fence Damage
San Jacinto River Waste Pits
June 18, 2014



Photo 3: One of four broken fence ties at a fence post south of I-10 and along the west bank of San Jacinto River (20140618_1.JPG)



Photo 4: Location of fence post with broken ties (20140618_3.JPG)